Mental Health- Prairie Building								BERSCH & ASSOCIATES LTD.							
			SAMPLE DATA												
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments
B		Tunnel	Sample	B51-ASB.29	17-Nov-12	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Prairie Building- Main Tunnel- Pipeline fitting on small white line, above head, adjacent entry doors to Pine Building	Lineal Pipe Insulation, Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the corridor. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place. There may be inaccessible fittings above the ducting, consider any fittings above ducting to be ACM.
B		Tunnel	Sample	B51-ASB.30	17-Nov-12	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Prairie Building- Main Tunnel- Pipeline fitting on large "HP-100" line, above head, adjacent entry doors to Pine Building	Lineal Pipe Insulation, Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the corridor. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place.
B		Tunnel	Sample	B51-ASB.39	17-Nov-12	Chrysotile	70%	Lineal Pipe Insulation	Good	3	Park Building- Main Tunnel- Lineal pipe insulation on small overhead line adjacent entry doors	Lineal Pipe Insulation, Pipeline Fitting Compound	Low	Manage	Asbestos-containing lineal pipe insulation was identified within the tunnel of the facility. The insulation was noted to be in good condition and it is our recommendation that the lineal pipe insulation be managed in place.
B		"Mattress Room" Storage Room	Sample	B51-ASB.31	17-Nov-12	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Prairie Building- "Mattress Room" Storage Room- Pipeline fitting on small white line, adjacent light fixture	Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the storage room. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place.
B		"2" Storage Room	Sample Rep	B51-ASB.31	17-Nov-12	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Prairie Building- "Mattress Room" Storage Room- Pipeline fitting on small white line, adjacent light fixture	Pipeline Fitting Compound	Moderate	Encapsulate	Encapsulate end of lineal line where exposed mud is present, adjacent unit heater.
B		Storage Room adjacent "3" Storage Room	Sample Rep	B51-ASB.31	17-Nov-12	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Prairie Building- "Mattress Room" Storage Room- Pipeline fitting on small white line, adjacent light fixture	Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the storage room. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place. There may be inaccessible fittings above the ducting, consider any fittings above ducting to be ACM.
B		"3" Storage Room	Sample Rep	B51-ASB.33	17-Nov-12	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Prairie Building- Mechanical Room- Pipeline fitting on small white "LP-15" line, adjacent ceiling	Lineal Pipe Insulation, Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the "3"storage room. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place
B		"3" Storage Room	Sample	B51-ASB.34	17-Nov-12	Chrysotile	70%	Lineal Pipe Insulation	Good	3	Prairie Building- "3" Storage Room- Lineal pipe insulation on small line, above entry door, coming in room 4'	Lineal Pipe Insulation, Pipeline Fitting Compound	Low	Manage	Asbestos-containing lineal pipe insulation was identified within the "3" storage room of the facility. The insulation was noted to be in good condition and it is our recommendation that the lineal pipe insulation be managed in place.
B		Emo Hospital Storage	Sample Rep	B51-ASB.31	17-Nov-12	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Prairie Building- "Mattress Room" Storage Room- Pipeline fitting on small white line, adjacent light fixture	Pipeline Fitting Compound	Moderate	Remove	Remove 1 damaged fitting 25' in from entry door.
B		"IT Storage"	Sample	B51-ASB.36	17-Nov-12	Chrysotile	50%	Fireproofing	Good	3	Prairie Building- "IT Storage"- Fire proofing material on ceiling	Fireproofing	Low/Mod	Manage	Asbestos fireproofing was found on the ceiling within the storage room. The fireproofing was noted in good condition and intact on the ceiling. It is our recommendation that the fireproofing be managed in place.
B		Mechanical Room	Sample	B51-ASB.32	17-Nov-12	Chrysotile	60%	Pipeline Fitting Compound	Poor	1	Prairie Building- Mechanical Room- Pipeline fitting on large white "LP-15" line, adjacent ceiling	Pipeline Fitting Compound	Mod/High	Repair	Repair 10 damaged areas where the mud compound is exposed in the northeast corner. Repair 2 damaged areas on the east side of the fan units. Repair 2 damaged fittings along the south wall, behind the fan unit, and clean up debris on ground, ledge, and fan unit in the adjacent area.
B		Mechanical Room	Sample	B51-ASB.33	17-Nov-12	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Prairie Building- Mechanical Room- Pipeline fitting on small white "LP-15" line, adjacent ceiling	Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the mechanical room. In general, these fittings were observed in good condition. It is our recommendation that these fittings be managed in place.

Mental Health- Prairie Building								BERSCH & ASSOCIATES LTD.							
			SAMPLE DATA												
	Room		SAMPLE	Sample	Date	Asbestos	% of	Tradename			Description of	Asbestos Content	Potential for	Recommended	
Floor	Number	Use	SAMPLE REP	ID	DD/MM/YY	Type	Asbestos	ACM Product	Condition	Priority	Sample Location	In Area	Disturbance	Action	Comments
M		Office	Sample	B51-ASB.35	17-Nov-12	Chrysotile	1-5%	Vinyl Asbestos Tile	Good	3	Prairie Building- Office- 12" by 12" floor tile, white with black spec	Vinyl Asbestos Floor Tile	Low	Manage	The majority or the main floor of the building has asbestos floor tiles. However rooms such as bathrooms, and tub rooms did not contain any asbestos floor tile. The floor tile was noted in good condition and is our recommendation that the tile be managed in place until renovations warrant removal.