

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
C		Crawlspace	Sample	B51-ASB.14	08-Aug-12		None	Pipeline Fitting Compound			Crawlspace- Pipe fitting on small line, adjacent crawlspace entry door #2	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Crawlspace	Sample	B51-ASB.8	08-Aug-12		None	Pipeline Fitting Compound			Crawlspace- Pipe fitting on medium line, 20' northwest of crawlspace entry door #1	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Crawlspace	Sample	B51-ASB.26	08-Aug-12		None	Pipeline Fitting Compound			Crawlspace- Pipe fitting on small line, adjacent crawlspace entry door	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Crawlspace	Sample	B51-ASB.27	08-Aug-12		None	Pipeline Fitting Compound			Crawlspace- Pipe fitting on medium line near entry door #1	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Crawlspace	Sample	B51-ASB.28	08-Aug-12		None	Pipeline Fitting Compound			Crawlspace- Pipe fitting on small line near perimeter wall	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Boiler Room	Sample	B51-ASB.1	08-Aug-12		None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on large "No Asbestos" line, close to the ceiling, adjacent pump "7" panel	Pipeline Fitting Compound			No asbestos detected. No action required.	
B		Boiler Room	Sample	B51-ASB.2	08-Aug-12		None	Pipeline Fitting Compound			Boiler Room- Damage pipe fitting on large line, 4' off the ground, by pump panels	Pipeline Fitting Compound			No asbestos detected. No action required.	
B		Boiler Room	Sample	B51-ASB.3	08-Aug-12		None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on old medium line, in-between blue boilers # 3 and 4, adj, to floor	Pipeline Fitting Compound			No asbestos detected. No action required.	
B		Boiler Room	Sample	B51-ASB.4	08-Aug-12		None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on old medium line, adjacent gray expansion tank	Pipeline Fitting Compound			No asbestos detected. No action required.	
B		Boiler Room	Sample	B51-ASB.5	08-Aug-12		None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on medium "HWS" line, adjacent boiler #3	Pipeline Fitting Compound			No asbestos detected. No action required.	
B		Boiler Room	Sample	B51-ASB.6	08-Aug-12	Chrysotile	70%	Pipeline Fitting Compound	Good	3	Boiler Room- Pipe fitting on small line, found in hole in the ceiling	Pipeline Fitting Compound	Low	Manage	<b>Consider all pipeline fittings above the drywall ceiling to be ACM unless otherwise tested, except the fittings in the cut out hole by the female locker room.</b>	
B		Boiler Room	Sample	B51-ASB.22	08-Aug-12		None	Fire-Stop Material			Boiler Room- Fire-stop material at pipe penetrations adjacent large duct units	Pipeline Fitting Compound			No asbestos detected. No action required.	

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
B		Electrical/ Water Softener Room	Sample	B51-ASB.7	08-Aug-12	Chrysotile	60%	Pipeline Fitting Compound	Good	3	Electrical/ Water Softener Room- Pipe fitting on medium line, above drywall, found in hole in the ceiling	Pipeline Fitting Compound	Low	Manage	Asbestos-containing fittings were identified in the electrical/ water softener room. In general, these fittings were observed in moderate condition. It is our recommendation that these fittings be managed in place.	
B		Basement Corridor	Sample	B51-ASB.9	08-Aug-12		None	Pipeline Fitting Compound			Basement Corridor- Pipe fitting on small line, adjacent women's locker room door, found in hole in the ceiling	No accessible ACM			<b>Consider all pipeline fittings above the drywall ceiling to be ACM unless otherwise tested, except the fittings in the cut out hole by the female locker room.</b>	
B		Basement Corridor	Sample	B51-ASB.10	08-Aug-12		None	Vinyl Floor Tile			Basement Corridor- 12" by 12" floor tile, yellow	No accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Shop Storage	Sample	B51-ASB.11	08-Aug-12		None	Pipeline Fitting Compound			Shop Storage- Pipe fitting on small line, above dry wall, found in hole in ceiling	Asbestos Sheet Flooring, Pipeline Fitting Compound			No asbestos detected. No action required	
B		Shop Storage	Sample	B51-ASB.12	08-Aug-12		None	Vinyl Floor Tile			Shop Storage- 12" by 12" floor tile, beige with white and black spec	Asbestos Sheet Flooring, Pipeline Fitting Compound			No asbestos detected. No action required	
B		Shop Storage	Sample Rep	B51-ASB.13	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Basement Storage- Sheet flooring found on shelves	Asbestos Sheet Flooring, Pipeline Fitting Compound	Low	Manage	The Sheet flooring was found on the shelves.	
B		Shop Storage	Sample Rep	B51-ASB.7	08-Aug-12	Chrysotile	60%	Pipeline Fitting Compound	Poor	2	Electrical/ Water Softener Room- Pipe fitting on medium line, above drywall, found in hole in the ceiling	Asbestos Sheet Flooring, Pipeline Fitting Compound	Moderate	Cleanup/Manage	Clean up the pipeline fitting debris laying on the dry wall by the hole in the roof.	
B		Basement Storage	Sample	B51-ASB.13	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Basement Storage- Sheet flooring found on shelves	Asbestos Sheet Flooring	Low	Manage	The Sheet flooring was found on the shelves.	
B		Mending Room	Sample	B51-ASB.15	08-Aug-12		None	Vinyl Floor Tile			Mending Room- 12" by 12" floor tile, cream and blue steak pattern	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Corridor Adjacent Laundry	Sample	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the corridor. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Laundry	Sample	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the Laundry room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Corridor	Sample	B51-ASB.18	08-Aug-12		None	Ceiling Tiles			Corridor Adjacent Laundry- 2' by 4' ceiling tile, with rough surface and pin holes	No asbestos detected. No action Required.			No asbestos detected. No action Required.	
M		Corridor	Sample	B51-ASB.21	08-Aug-12		None	Ceiling Tiles			Corridor- 2' by 4' ceiling tile, pin hole pattern	No asbestos detected. No action Required.			No asbestos detected. No action Required.	
M		Conference Room	Sample	B51-ASB.23	08-Aug-12	Chrysotile	30%	Transite Pipe	Good	3	Conference Room- Transite Pipe	Transite Pipe	Low	Manage	Asbestos-containing transite pipe was identified in the conference room. In general, the transite pipe was observed in good condition. It is our recommendation that the transite pipe be managed in place.	

Gateway Lodge			BERSCH & ASSOCIATES LTD.												
			SAMPLE DATA												
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments
M		Soiled Utility/ House Keeping	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Janitors Closet adj 22	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the janitors closet. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Clean Linen adj South Lounge	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the linen room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Clean Utility	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Mending Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the mending room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Chemical Storage adj Laundry	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the chemical storage. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Linen Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the linen room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Janitors Closet adj Kitchen	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the janitors closet. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Utility Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		South Wing	Sample Rep	B51-ASB.23	08-Aug-12	Chrysotile	30%	Transite Pipe	Good	3	Conference Room- Transite Pipe	Transite Pipe	Low	Manage	Asbestos-containing transite pipe was identified in the south wing. In general, the transite pipe was observed in good condition. It is our recommendation that the transite pipe be managed in place.
M		South Lounge	Sample Rep	B51-ASB.23	08-Aug-12	Chrysotile	30%	Transite Pipe	Good	3	Conference Room- Transite Pipe	Transite Pipe	Low	Manage	Asbestos-containing transite pipe was identified in the south lounge. In general, the transite pipe was observed in good condition. It is our recommendation that the transite pipe be managed in place.
M		East Wing	Sample Rep	B51-ASB.23	08-Aug-12	Chrysotile	30%	Transite Pipe	Good	3	Conference Room- Transite Pipe	Transite Pipe	Low	Manage	Asbestos-containing transite pipe was identified in the east wing. In general, the transite pipe was observed in good condition. It is our recommendation that the transite pipe be managed in place.

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		I.T. Room adj Offices	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Storage Room adj 23	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the storage room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Soiled Utility across from 19	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Clean Utility across from 18	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the utility room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Food Storage	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the food storage room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	1	CHP	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the CHP room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	2	CHP	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the CHP room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	1	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	2	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	3	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	4	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	5	Res Room	Sample Rep	B51-ASB.24	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 61- Sheet flooring, green and white stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	6	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	7	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	8	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	9	Res Room	Sample Rep	B51-ASB.24	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 61- Sheet flooring, green and white stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	10	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	11	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	12	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	13	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	15	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	16	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	17	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	18	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	19	Res Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	20	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	21	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	22	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	23	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	24	Res Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	25	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	26	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	27	Res Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	28	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	29	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry-Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Gateway Lodge			BERSCH & ASSOCIATES LTD.												
			SAMPLE DATA												
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments
M	30	Res Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	31	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	32	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	33	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	34	Res Room	Sample Rep	B51-ASB.17	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Laundry- Sheet flooring, tiny dark stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	35	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	36	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	37	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	38	Res Room	Sample Rep	B51-ASB.16	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Corridor Adjacent Laundry- Sheet flooring, small irregular stone pattern, with yellow colours	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	39	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	40	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	41	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.

Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	42	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	43	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	44	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	45	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	46	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	47	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	48	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	49	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	50	Res Room	Sample Rep	B51-ASB.24	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 61- Sheet flooring, green and white stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	51	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	53	Res Room	Sample	B51-ASB.19	08-Aug-12		None	Stipple Ceiling Texture			Room 53- Stipple ceiling texture	Asbestos Sheet Flooring			Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	53	Res Room	Sample	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	



Gateway Lodge			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	54	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	55	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	56	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	57	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	58	Res Room	Sample Rep	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	59	Res Room	Sample	B51-ASB.25	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 59- Sheet flooring, brown color stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	60	Res Room	Sample Rep	B51-ASB.20	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 53- Sheet flooring, pink and blue stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	61	Res Room	Sample	B51-ASB.24	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Res Room 61- Sheet flooring, green and white stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	