

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
C		Old Crawspace	Sample	B51-ASB.13	08-Aug-12	Chrysotile	30%	Transite Pipe	Good	3	Crawspace- Transite pipe	Transite Pipe	Low	Manage	Asbestos-containing transite pipe was identified in the crawspace. In general, the transite pipe was observed in good condition. It is our recommendation that the transite pipe be managed in place.	
M	1	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	2	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	2	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	4	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	5	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	6	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	7	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	8	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	9	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	10	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	11	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	12	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	13	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	14	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	15	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	16	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	17	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	18	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	19	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	20	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	21	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	22	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	23	Res Room	Sample	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	23	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	24	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	25	Res Room	Sample Rep	B51-ASB.11	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Room 23- Sheet flooring, small irregular square pattern with dark brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	26	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	28	Res Room	Sample	B51-ASB.7	08-Aug-12	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	Room 28- Sheet flooring on crawl space access, small square pattern	Asbestos Sheet Flooring	Low	Manage	FLOORING WAS REMOVED FROM CRAWLSPACE ACCESS HATCH.	
M	51	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	53	Res Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Boiler Room	Sample	B51-ASB.1	08-Aug-12	None	None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on medium light blue line on boiler #1	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Boiler Room	Sample	B51-ASB.2	08-Aug-12	None	None	Pipeline Fitting Compound			Boiler Room- Pipe fitting on medium dark blue line leading off of boiler	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Boiler Room	Sample	B51-ASB.3	08-Aug-12	None	None	Pipeline Fitting Compound			Boiler Room- Boiler breaching leading off of boiler #1	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		Maintenance Workshop	Sample	B51-ASB.5	08-Aug-12	None	None	Pipeline Fitting Compound			Maintenance Workshop- Pipe fitting on small blue line adjacent entry door	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Pump Room	Sample	B51-ASB.6	08-Aug-12	None	None	Vinyl Floor Tile			Pump Room adjacent Kitchen- 12" by 12" floor tile, yellow with reddish streak/spec	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Corridor adjacent Room 27	Sample	B51-ASB.8	08-Aug-12	None	None	Pipeline Fitting Compound			Corridor adjacent Room 27- Pipe fitting on small line adjacent room 27	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Center Lounge	Sample	B51-ASB.9	08-Aug-12	None	None	Stipple Ceiling Texture			Center Lounge- Stipple ceiling texture	Asbestos Sheet Flooring			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		Center Lounge	Sample	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the center lounge. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Generator Room	Sample	B51-ASB.12	08-Aug-12	None	None	Duct Expansion			Generator Room- Duct expansion gasket	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		SW Lounge	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the SW lounge. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		SW Lounge Entrance	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the SW lounge entrance. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		SE Lounge	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the SE lounge. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Linen Room adj. Room 1	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the linen room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Janitors Closet adj. Room 2	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the Janitors Closet. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		Hair Salon	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the hair salon. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Staff Washroom	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the washroom. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Public Washroom	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the washroom. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Administration Office	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the Administration Office. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Activity Director Office	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the Activity Director Office. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Solarium	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the solarium. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Solarium Entrance	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the solarium entrance. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Medical Room	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the medical room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Nurse Station	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the nurse station. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Soiled Linen	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the soiled linen. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Clean Linen	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the cleaned linen. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Staff Lounge	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the staff lounge. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Kamsack Nursing Home			BERSCH & ASSOCIATES LTD.												
			SAMPLE DATA												
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments
M		Corridor between SW Lounge and SE Lounge	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the corridor. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M		Corridor between Nurse Station and Centre Lounge	Sample Rep	B51-ASB.10	08-Aug-12	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Center Lounge- Sheet flooring, small irregular square pattern with light brown background	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the corridor. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
A		Attic Space	Sample	B51-ASB.4	08-Aug-12	Actinolite/ Tremolite	>0.1%	Zonolite Insulation	Good	3	Attic Space adjacent Boiler Room- Zonolite insulation	Zonolite Insulation	Low	Manage	The Zonolite was found at several attic accesses, consider all zonolite to be >0.1% Actinolite/ Tremolite unless additional sampling proves otherwise. This material may be managed in place until future renovations/ maintenance, causing disruption of the material, is conducted. The action then may warrant removal of the insulation material to prevent disruption. People entering the attic space may do so wearing the proper PPE and following the appropriate low-risk procedures.