

Langenburg Health Care Complex			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
C		Nurse Station Crawspace	Sample	B51-ASB.14	25-Sep-12	None		Pipeline Fitting Compound			Nurse Station Crawspace- Pipe fitting on small blue line, near entry	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Nurse Station Crawspace	Sample	B51-ASB.15	25-Sep-12	None		Pipeline Fitting Compound			Nurse Station Crawspace- Pipe fitting on medium white line, near entry	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Nurse Station Crawspace	Sample	B51-ASB.16	25-Sep-12	None		Pipeline Fitting Compound			Nurse Station Crawspace- Pipe fitting on small teal line, adjacent wall, near entry	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
C		Crawspace	Sample	B51-ASB.12	25-Sep-12	None		Pipeline Fitting Compound			317 Crawspace- Small fitting adjacent entrance	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Care Home Boiler Room	Sample	B51-ASB.1	25-Sep-12	None		Pipeline Fitting Compound			Care Home Boiler Room- Pipe fitting on medium light green line adjacent cement pillar, adjacent "glycol" pump #1 & #2	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Care Home Boiler Room	Sample	B51-ASB.2	25-Sep-12	None		Pipeline Fitting Compound			Care Home Boiler Room- Pipe fitting on large green line overhead, coming off of boiler	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Care Home Boiler Room	Sample	B51-ASB.3	25-Sep-12	None		Boiler Breaching			Care Home Boiler Room- Boiler Breaching coming off of boiler	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Care Home Boiler Room	Sample	B51-ASB.4	25-Sep-12	None		Pipeline Fitting Compound			Care Home Boiler Room- Damaged pipe fitting on small blue line adjacent north wall, adjacent tank	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Care Home Boiler Room	Sample	B51-ASB.5	25-Sep-12	None		Pipeline Fitting Compound			Care Home Boiler Room- Pipe fitting on large blue line, overhead adjacent "P2" pump	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
B		Basement Storage	Sample	B51-ASB.6	25-Sep-12	None		Pipeline Fitting Compound			Basement Storage- Pipe fitting on small blue line in the northwest corner of room	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	

Langenburg Health Care Complex			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		Dining Area	Sample	B51-ASB.13	25-Sep-12		None	Vinyl Sheet Flooring			Dining Area- Sheet flooring, multicoloured cloudy pattern	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.	
M		100 Wing	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the corridor. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Wheel Chair Storage	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the wheel chair storage. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Storage Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the storage room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Med Room Office	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the med room office. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		House Keeping Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the house keeping room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Washroom	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the washroom. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Nurse Station	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the nurse station. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	103	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	104	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	105	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Langenburg Health Care Complex			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	106	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	107	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	108	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	109	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	110	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	111	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	112	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	113	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	114	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	115	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	116	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		200 Wing	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	The asbestos flooring only goes till rooms 209 and 210. the newer 1977 addition flooring does not contain asbestos.	

Langenburg Health Care Complex			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		Staff Dinning	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the staff room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	201	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	202	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	203	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	204	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	205	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	206	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	207	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	208	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	209	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M	210	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	
M		Female Locker Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the female locker room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.	

Langenburg Health Care Complex			BERSCH & ASSOCIATES LTD.												
			SAMPLE DATA												
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments
M		300 Wing	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	The asbestos flooring only goes till rooms 309 and 310. the newer 1977 addition flooring does not contain asbestos.
M		300 Wing	Sample	B51-ASB.9	25-Sep-12		None	Ceiling Tiles			South Wing- 2' by 4' ceiling tile, tiny pin holes and lots of irregular gashes	Asbestos Sheet Flooring			No asbestos detected. No action required.
M		300 Wing	Sample	B51-ASB.10	25-Sep-12		None	Ceiling Tiles			South Wing- 2' by 4' ceiling tile, lots of tiny pin holes and a few gashes	Asbestos Sheet Flooring			No asbestos detected. No action required.
M	303	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	305	Res Room	Sample	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	306	Res Room	Sample	B51-ASB.7	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 306- Sheet flooring, light brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	307	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	308	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	309	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	310	Res Room	Sample Rep	B51-ASB.8	25-Sep-12	Chrysotile	30	Asbestos Sheet Flooring	Good	3	Room 305- Sheet flooring, brown small stone pattern	Asbestos Sheet Flooring	Low	Manage	Asbestos was detected within the vinyl asbestos sheet flooring located within the resident room. Overall, this material was noted in good condition and may be managed in place until renovations warrant removal.
M	318	Res Room	Sample	B51-ASB.11	25-Sep-12		None	Vinyl Sheet Flooring			Room 318- Sheet flooring- brown and greyish/ green stone pattern	No Accessible ACM			No asbestos detected. No action required. No accessible asbestos-containing materials identified. Please note that there is a potential for asbestos to be present in concealed areas such as ceiling spaces, wall cavities and pipe chases located within the area.