

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B	OB3	SHPG/REC	Sample Rep.	B51-ASB75	18/02/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B	3	STORAGE	Sample Rep.	B51-ASB10	18/02/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	23	OFFICE	Sample Rep.	B51-ASB10	18/02/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	22	OFFICE	Sample Rep.	B51-ASB10	18/02/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	21	OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		MEN adj STORAGE 20	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		WOMEN adj STORAGE 20	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	20	STORAGE	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield
B	20	STORAGE	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	
B	19	OFFICE	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	
B	18	OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	17	OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	16	OFFICE	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	
B	15	OFFICE	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	
B	14	OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	13	OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		PHYSIO STORAGE	Sample	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	
B		PUMP ROOM	Sample	B51-ASB56	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Good	3	017-Small pipeline fitting behind the entry door	Low	Remove	Visible pipeline fittings are present.
B		STORAGE	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixtures contain a foil faced ACM heat shield
B		LADIES adj 14	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		LADIES adj 14	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixtures contain a foil faced ACM heat shield
B		HOUSEKEEPING adj OFFICE 16	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield
B		HOUSEKEEPING adj OFFICE 16	Sample Rep.	B51-ASB54	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	B4-Small pipeline fitting within the ceiling space adj. room 021 inside the fire doors in the south wing corridor	Low	Manage	Pipeline fittings are present within ceiling space
B		HOUSEKEEPING adj OFFICE 16	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B		KITCHEN	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		WAITING ROOM	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		CANE & WALKER STORAGE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		PHYSICAL OCCUPATIONAL & SPEACH THERAPY	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B		CORRIDOR adj STEAM PLANT	Sample Rep.	B51-ASB22	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Good	3	11-Medium overhead pipeline fitting at the north entry door	Low	Manage	Visible pipeline fittings are present
B		CORRIDOR adj STEAM PLANT	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB34	18/2/2006		none	Pipeline Fitting Compound	Bersch			B2-Condensate return to laundry pipeline fitting within the ceiling space 8 feet to the north of the link to the laundry entry-way adj. electrical room 16			
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB35	18/2/2006		none	Ceiling Tiles	Bersch			B2-2' X 4' ceiling tile with a two dia. hole pattern in the corner adj. the electrical room 16			
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB36	18/2/2006		none	Ceiling Tiles	Bersch			B2-2' X 4' ceiling tile with a pin hole pattern in the corner adj. the electrical room 16			
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB37	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	B2-1' X 1' white/beige streak marble-like floor tile	Low	Manage	
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB38	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	B2-Pipeline fitting above the suspended ceiling adj. the entry to the link to laundry adj. the northwest corner of the Soiled Laundry Room 18	Low	Remove	Pipeline fittings are present within ceiling space.
B		CORRIDOR adj MECANICAL ROOM	Sample	B51-ASB39	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	B2-Tar-coated pipeline fitting above the suspended ceiling adj. the entry to the link to laundry adj. the northwest corner of the Soiled Laundry Room 18	Low	Manage	Pipeline fittings are present within ceiling space
B	2.1	WATER SERV	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Poor	1	2-Small overhead pipeline fitting inside doorway	Moderate	Remove	Pipeline fittings are present within the ceiling space. Remove 1 fitting above the A/C unit within the ceiling space
B	2.1	WATER SERV	Sample	B51-ASB42	18/2/2006		none	Ceiling Tiles	Bersch			2.1-2' X 4' suspended ceiling tile			
B	2.1	WATER SERV	Sample	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Transite drainpipe is present within the ceiling space.
B	2.2	BIO MEDICAL WASTE COOLER	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Pipeline fittings are present within the ceiling space. The area is inaccessible to identify the fittings, consider all fittings within the ceiling space to be ACM.

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B		CORRIDOR adj PHARMACY STORAGE	Sample Rep.	B51-ASB37	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	B2-1' X 1' white/beige streak marble-like floor tile	Low	Manage	
B		CORRIDOR adj PHARMACY STORAGE	Sample Rep.	B51-ASB53	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Moderate	2	21-Small pipeline fitting above the shelving in the southeast corner	Low/Mod	Remove	Pipeline fittings are present within ceiling space. Fittings are present in the section of corridor adj. room 28.
B		HOUSEKEEPING	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Moderate	1	2-Small overhead pipeline fitting inside doorway	Low/Mod	Encapsulate	Encapsulate exposed pipeline fitting above door way.
B		CORRIDOR SOUTH WING	Sample	B51-ASB54	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	B4-Small pipeline fitting within the ceiling space adj. room 021 inside the fire doors in the south wing corridor	Low	Manage	Pipeline fittings are present within ceiling space
B		CORRIDOR SOUTH WING	Sample Rep.	B51-ASB37	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	B2-1' X 1' white/beige streak marble-like floor tile	Low	Manage	
B	1	MALE LOCKER ROOM	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present
B		CORRIDOR LAUNDRY	Sample	B51-ASB57	18/2/2006		none	Floor tile	Bersch			B5-1' X 1' beige/white & it brown streak floor tile			
B		CORRIDOR	Sample	B51-ASB58	18/2/2006		none	Floor tile	Bersch			B6-1' X 1' cream/fine streak floor tile			
B		CORRIDOR	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present
B	2	OFFICE	Sample	B51-ASB46	18/2/2006		none	Pipeline Fitting Compound	Bersch			6-Pipeline fitting above doorway			
B	2	OFFICE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present
B	2	OFFICE	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present
B	3	OFFICE	Sample	B51-ASB47	18/2/2006		none	Ceiling Tiles	Bersch			7-1' x 1' perforated ceiling tile			
B	3.1	STORAGE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present
B	4	OFFICE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Pipeline fittings are present within the ceiling space

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B	4	OFFICE	Sample	B51-ASB48	18/2/2006		none	Pipeline Fitting Compound	Bersch			8-Heating return pipeline fitting above the suspended ceiling to the right of the entrance			
B	4.1	OFFICE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Inaccessible pipeline fittings are present within the ceiling space. Consider all fittings within ceiling space to be ACM
B	5	OFFICE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Pipeline fittings are present within the ceiling space
B	5.1	OFFICE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Inaccessible pipeline fittings are present within the ceiling space. Consider all fittings within ceiling space to be ACM
B	5.1	STORAGE	Sample	B51-ASB49	18/2/2006		none	Parging Material	Bersch			9.1Parging material at the cut-out in the ceiling surface			No accessible ACM
B		CAFETERIA	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	fitting within the ceiling space on the east side adj. the MSDS station	Low	Manage	Pipeline fittings are present within ceiling space
B		CAFETERIA	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present
B	11	STEAMPLANT	Sample	B51-ASB17	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch			11-Mud compound on the north end of the header adj. the 1.5 hp sump pump in the northeast corner of the room			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB18	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch			11-Overhead valve fitting above the brine tank in the northeast corner			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB19	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch			11-Large overhead pipeline fitting behind the sodium chloride tank in the northeast corner			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB20	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch			11-Condensate pipeline fitting above the chemical control panel adj. the chemical tank			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB21	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Small pipeline fitting on the Dealk supply pipeline on the side of the #2 fibreglass tank adj. the northeast corner			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.

**YORKTON UNION HOSPITAL** **BERSCH & ASSOCIATES LTD.**

Room			Sample Data										Potential for		Recommended
Floor	Number	Use	Locations	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Sample Auditor	Condition	Priority	Description of Sample Location	Disturbance	Action	Comments
B	11	STEAMPLANT	Sample	B51-ASB22	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch			11-Medium overhead pipeline fitting at the north entry door			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB23	18/2/2006	Chrysotile	40%	Mechanical Insulation	Bersch			#1 & 2 boiler breeching adjacent the brick chimney stack adj. the mezz. Stairway			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB24	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Large overhead pipeline fitting on the condensate tank BY-PS adj. the emergency shower/eye-wash station east of the control room			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB25	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-CH pipeline fitting on the south side of #1 & 2 blue steel upright softener tanks			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB26	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Small pipeline fitting in the southwest corner on the platform above the Volcano Boiler			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB27	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Large valve assembly mud compound above the steam drum of the Volcano Boiler in the southwest corner of the plant			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB28	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Medium pipeline fitting on the walkway above the Volcano Boiler in the southwest corner of the plant			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB29	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Condensate tank supply pipeline fitting above the mezz. boiler supply compressor #1 behind the Hotwell tank			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB30	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Steam supply pipeline fitting on the mezz. level behind the deaerator tank			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB31	18/2/2006	Chrysotile	60%	Mechanical Insulation	Bersch			11-DHW #2 tank insulation on the mezz. level			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B	11	STEAMPLANT	Sample	B51-ASB32	18/2/2006	Amosite	40%	Mechanical Insulation	Bersch			11-#1 Boiler steam drum insulation on the mezz. level			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB33	18/2/2006	Chrysotile	60%	Mechanical Insulation	Bersch			11-Laundry preheat unit parging material over cork insulation in the mezz. level fan room			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB74	18/2/2006		none	Pipeline Fitting Compound	Bersch			11-Small pipeline fitting along the west wall behind #1 & 2 boilers			All pipeline fittings have been removed in the steam plant. There is one fittings however over boiler 1 that is inaccessible to mark or test. Consider the fitting to be acm unless otherwise tested.
B	11	STEAMPLANT	Sample	B51-ASB78	08/11/2012	Chrysotile	40%	Gasket material	Bersch	Mod/Good	1	Steam Plant- Black gasket material hanging on the south wall	Low/Mod	Remove	Maintenance said they were going to removal the gasket ASAP when the survey was being done.
B	11	STEAMPLANT	Sample	B51-ASB76	08/11/2012		none	Insulation material	Bersch			Steam Plant Insulation material (brick like)			
B	11	STEAMPLANT	Sample	B51-ASB77	08/11/2012		none	Lineal Pipe Insulation	Bersch			Steam Plant Lineal pipe insulation adjacent 'brick like' insulation			
B	11	STEAMPLANT	Sample	B51-ASB79	08/11/2012		none	Gasket material	Bersch			Steam Plant Green gasket material hanging on the south wall			
B	11	STEAMPLANT	Sample	B51-ASB80	08/11/2012		none	Debris	Bersch			Steam Plant White debris in northwest corner adjacent old black boiler			
B		FEMALE LOCKER	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Mod/Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present. A few pipeline fittings are inaccessible to identify with red paint. Consider all fittings to be ACM.
B	12.1	PIPE CHASE	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Visible pipeline fittings are present. A few fittings are inaccessible to identify, consider all fittings in the area to be ACM.
B	13	CONFERENCE (STORAGE)	Sample Rep.	B51-ASB38	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Moderate	2	B2-Pipeline fitting above the suspended ceiling adj. the entry to the link to laundry adj. the northwest corner of the Soiled Laundry Room 18	Low/Mod	Remove	Pipeline fittings are present within ceiling space. Remove 3 small fittings adj. the east supply air grille and HEPA vacuum the debris on the ceiling tile immediately below the fittings
B	13	CONFERENCE (STORAGE)	Sample	B51-ASB50	18/2/2006		none	Pipeline Fitting Compound	Bersch			13-Large pipeline fitting within the ceiling space adj. the east vertical column along the south wall			
B		MECHANICAL	Sample	B51-ASB12	18/2/2006		none	Pipeline Fitting Compound	Bersch			14-Large valve assembly compound above P-2 adj. the sulphuric acid barrel			

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B		MECHANICAL	Sample	B51-ASB13	18/2/2006		none	Pipeline Fitting Compound	Bersch			14-Large pipeline fitting above P-3 adj. the sulphuric acid barrel			
B		MECHANICAL	Sample	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Poor	1	14-Pipeline fitting above the east doorway	Low/Mod	Remove	Visible pipeline fittings are present. Remove 1 fitting above the #1 chiller and HEPA vacuum the top of the chiller. Remove 1 small overhead fitting adjacent the south door. A few fittings are inaccessible above #2 convertor along the north wall, therefore they were not identified with red paint.
B		MECHANICAL	Sample	B51-ASB15	18/2/2006		none	Pipeline Fitting Compound	Bersch			14-Hot water heating supply pipeline fitting beside the conv-2 adj. the medical air pump #2			
B		FANROOM	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Moderate	1	14-Pipeline fitting above the east doorway	Low/Mod	Repair/Remove	Visible pipeline fittings are present. Remove 1 fitting below the light switch on the west wall at the floor level.
B		FANROOM	Sample	B51-ASB16	18/2/2006		none	Pipeline Fitting Compound	Bersch			15-Chilled water supply pipeline fitting between fan units			
B		FANROOM	Sample	B51-ASB81	08/11/2012		none	Debris	Bersch			Fan Room adj. Steam Plant Debris on fan unit			
B		ELECTRICAL	Sample	B51-ASB73	18/2/2006		none	Pipeline Fitting Compound	Bersch			16-Small pipeline fitting along the west wall behind #1 & 2 boilers			
B		FIRE ALARM CONTROL ROOM	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present.
B		DIETARY	Sample	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Moderate	1	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low/Mod	Remove	Pipeline fittings are present within ceiling space and visible fittings are also present. Remove 3 fittings at the unit heater to the north of 17.3 and 1 above the ceiling tile in the same location. Remove 1 fitting above the entry into the produce freezer.
B		DIET OFFICE	Sample Rep.	B51-ASB10	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16.1-9" X 9" beige/white streak floor tile	Low	Manage	
B	0.1	DIET OFFICE	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low	Manage	Inaccessible pipeline fittings are present within ceiling space.
B		HOUSEKEEPING adj dish washer	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low	Manage	Visible pipeline fittings are present
B		KITCHEN	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low	Manage	Pipeline fittings are present within ceiling space

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
B		CLINICAL DIETITION	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low	Manage	Pipeline fittings are present within ceiling space
B		FOOD NUTRITION SERVICES	Sample Rep.	B51-ASB65	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Poor/Mod	1	27-Small tar-coated pipeline fitting within the ceiling space on the east side adj. the MSDS station	Low/Mod	Remove	Pipeline fittings are present within ceiling space. Remove 1 medium fitting within the west side of the room.
B		CHUTE LAUNDRY	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		CHUTE LAUNDRY	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present
B		X RAY STORAGE	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		X RAY STORAGE	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Mod/Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present
B		PHARMACY	Sample Rep.	B51-ASB39	18/2/2006	Chrysotile	20%	Pipeline Fitting Compound	Bersch	Good	3	B2-Tar-coated pipeline fitting above the suspended ceiling adj. the entry to the link to laundry adj. the northwest corner of the Soiled Laundry Room 18	Low	Manage	Pipeline fittings are present within ceiling space
B		PHARMACY STORAGE	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixtures contain a foil faced ACM heat shield
B		PHARMACY STORAGE	Sample	B51-ASB52	18/2/2006		none	Pipeline Fitting Compound	Bersch			21-CHWR overhead pipeline fitting along the east wall			
B		PHARMACY STORAGE	Sample Rep.	B51-ASB53	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Good	3	21-Small pipeline fitting above the shelving in the southeast corner	Low	Manage	Visible pipeline fittings are present
		IT ROOM	Sample	B51-ASB53	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Good	3	21-Small pipeline fitting above the shelving in the southeast corner	Low	Manage	Visible pipeline fittings are present
B		MEN adj PHARMACY STORAGE	Sample	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield
B		SECURITY	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		PHARMACY	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		PHARMACY	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Mod/Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present. ACM pipeline fittings are also present within the ceiling space
B		PHARMACY STORAGE	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		FUME HOODS	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	
B		FUME HOODS	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Mod/Good	3	14-Pipeline fitting above the east doorway	Low	Manage	ACM pipeline fittings are present within the ceiling space
B		DIRECTOR OF PHARMACY	Sample Rep.	B51-ASB11	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	16-1' X 1' white/brown streak floor tile	Low	Manage	



**YORKTON UNION HOSPITAL** **BERSCH & ASSOCIATES LTD.**

Room		Sample Data										Potential for		Recommended	
Floor	Room Number	Use	Locations	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Sample Auditor	Condition	Priority	Description of Sample Location	Disturbance	Action	Comments
B		DUCT SHAFT	Sample	B51-ASB9	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Poor	1	B25-Overhead pipeline fitting on the steamline adj. the west wall	High	Remove	Remove 6 more damaged pipeline fittings that are still present in the room, Clean up debris laying on the electrical box and on the ground.
B		STORES DEPARTMENT	Sample	B51-ASB63	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Moderate	2	27-Small pipeline fitting above the east side entry from the ship/rec	Low/Mod	Encapsulate	Encapsulate one pipeline fitting in the northwest corner, above desk, above ceiling tile.
B		STORES DEPARTMENT	Sample	B51-ASB64	18/2/2006		none	Pipeline Fitting Compound	Bersch			27-Small pipeline fitting above the east side entry from the ship/rec			
B		STORES DEPARTMENT	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
		STAIRS adj STORES DEMARMENT	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Good	3	14-Pipeline fitting above the east doorway	Low	Manage	
B		STORES	Sample Rep.	B51-ASB63	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Poor	1	27-Small pipeline fitting above the east side entry from the ship/rec	Low/Mod	Remove	Remove 4 pipeline fittings along the east wall that are damaged
B		SE STORES adj DEPARTMENT	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B		SOLUTION ROOM adj STORES	Sample	B51-ASB82	08/11/2012	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	Solution Room- Transite drain pipe	Low	Manage	Visible transite drainpipe is present.
B		DECONTAMINATION	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B		REGIONAL INFECTION PREVENTION & CONTROL	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B		IPAC MEETING ROOM	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B		CORRIDOR adj STORES & DECONTAMINATION	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
B		YORKTON REGIONAL HEALTH CENTRE ADMINSTRATIVE OFFICES AREA	Sample Rep.	B51-ASB53	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Mod/Good	3	21-Small pipeline fitting above the shelving in the southeast corner	Low	Manage	Pipeline fittings are present within ceiling space. Inaccessible fittings are located within the closed ceiling above the suspended ceiling. Consider all pipeline fittings to be ACM
B		AUTOPSY	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Pipeline fittings are present within ceiling space.
B		MORGE	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield. Pipeline fittings were noted above the inaccessible ceiling space
B		HISTOLOGY	Sample Rep.	B51-ASB41	18/2/2006	Chrysotile	40%	Pipeline Fitting Compound	Bersch	Good	3	2-Small overhead pipeline fitting inside doorway	Low	Manage	Pipeline fittings are present within ceiling space.
B		WASHROOM (Lab Basement)	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room	Use	Locations	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Sample Auditor	Condition	Priority	Description of Sample Location	Potential for Disturbance	Recommended Action	Comments	
B	CO ED LOCKER ROOM (Lab Basement)	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield	
B	LOCKER ROOM (Lab Basement)	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixture contains a foil faced ACM heat shield	
B	HOUSEKEEPING (Lab Basement)	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Poor	1	22-Incandescent light fixture heat shield material	Moderate	Remove	Remove the foil faced ACM heat shield	
B	MECHANICAL	Sample	B51-ASB59	18/2/2006		none	Pipeline Fitting Compound	Bersch			35-P.Con.R. pipeline fitting to the left of the carbon dioxide tanks			No accessible ACM	
B	MECHANICAL	Sample	B51-ASB60	18/2/2006		none	Pipeline Fitting Compound	Bersch			35-DHW pipeline fitting along the east wall behind the carbon dioxide tank			No accessible ACM	
B	MECHANICAL	Sample	B51-ASB61	18/2/2006		none	Pipeline Fitting Compound	Bersch			35-HPC return pipeline fitting straight into the room along the floor			No accessible ACM	
B	MECHANICAL	Sample	B51-ASB62	18/2/2006		none	Pipeline Fitting Compound	Bersch			35-Pipeline fitting to the left of the entrance			No accessible ACM	
B	NORTHEAST MECHANICAL	Sample	B51-ASB83	08/11/2012		none	Pipeline Fitting Compound	Bersch			Northeast Mechanical Room Pipeline fitting on medium LPS line near roof				
B	NORTHEAST MECHANICAL	Sample	B51-ASB84	08/11/2012		none	Pipeline Fitting Compound	Bersch			Northeast Mechanical Room Pipeline fitting on 'HEATING RETURN LINE' near roof				
B	NORTHEAST MECHANICAL	Sample	B51-ASB85	08/11/2012		none	Ceiling Tiles	Bersch			Northeast Mechanical Room 2' by 4' ceiling tile				
B	NW STAIRWELL	Sample Rep.	B51-ASB37	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	B2-1' X 1' white/beige streak marble-like floor tile	Low	Manage		
B	STAIRWELL (adj mech)	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Mod/Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present	
B	S4 STAIRWELL (stores department)	Sample Rep.	B51-ASB14	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Mod/Good	3	14-Pipeline fitting above the east doorway	Low	Manage	Visible pipeline fittings are present	
B	LAUNDRY	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Transite drain pipe is present throughout various areas of laundry. Refer to door jam labels. The drain pipe was too high in some areas to label, consider all cement drain pipe to be ACM.	
G	FIRST WEST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The light fixtures contain a foil faced ACM heat shield. The majority of the washrooms throughout the wing contain similar heat shields, management is the recommended action within these areas.	

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
G		FIRST WEST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
G		FIRST EAST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Poor/Mod	1	22-Incandescent light fixture heat shield material	Low/Mod	Remove	The light fixtures contain a foil faced ACM heat shield. Remove either the whole fixture or the heat shield within the housekeeping room on the east end of the corridor. The majority of the washrooms throughout the wing contain similar heat shields, management is the recommended action within these areas
G		FIRST EAST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
		ICU WAITING ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU WAITING BATH ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU RESPRATORY SERVICES	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	Not all pipeline fittings were accessible due to ducting and ceiling tile.
		ICU STAFF ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		NURSES DESK/ MAIN AREA ICU	Sample	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
	6	ICU RES ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU CONFERENCE ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU NURSING UNIT MANAGER	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU ELECTRICAL ROOM	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Good	3	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low	Manage	
		ICU SOUTH CORRIDOR	Sample Rep.	B51-ASB66	18/2/2006	Chrysotile	30%	Pipeline Fitting Compound	Bersch	Moderate	2	ICU-Pipeline fitting above the ceiling tile inside the double entry doors	Low/Mod	Repair	Repair/ Remove 2 fittings in the southeast corner adjacent window and repair a fittings adjacent the
G		DOCTORS LOUNGE	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Consider all cement drain pipe throughout the hospital to be ACM
G		DOCTORS LOCKER ROOM	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Consider all cement drain pipe throughout the hospital to be ACM

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
G		DOCTORS WASHROOM	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Consider all cement drain pipe throughout the hospital to be ACM
G		LABORATORY	Sample	B51-ASB67	18/2/2006		none	Fireproofing	Bersch			Lab-Fireproofing within the ceiling space			No accessible ACM
G	S1	STAIRWELL	Sample Rep.	B51-ASB37	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	B2-1' X 1' white/beige streak marble-like floor tile	Low	Manage	
2		SECOND WEST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the washrooms throughout the wing contain an asbestos foil-faced heat shield, management of this material is recommended.
2		SECOND WEST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" It green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the floor plans. Areas throughout the hospital that have floor tile present is recommended that additional bulk sampling is conducted in the future if flooring upgrades are scheduled within the affected areas
2		SECOND EAST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the washrooms throughout the wing contain an asbestos foil-faced heat shield, management of this material is recommended.
2		SECOND EAST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" It green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
2		SECOND SOUTH	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the patient rooms throughout the wing contain asbestos foil-faced heat shields, management of this material is recommended.
2		SECOND SOUTH	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" It green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
2	2	PATIENT	Sample	B51-ASB68	18/2/2006		none	Vinyl Sheet Flooring	Bersch			2-Second floor patient room sheet floor covering			No accessible ACM
2		WEST FAN RM	Sample Rep.	B51-ASB75	18/2/2006	Chrysotile/ Crocidolite	30%, 10%	Transite Pipe	Bersch	Good	3	2.1-Housekeeping - transite drainpipe within ceiling space	Low	Manage	Visible transite drainpipe is present.
3	300	STAFFLOUNGE	Sample	B51-ASB69	18/2/2006		none	Vinyl Sheet Flooring	Bersch			300-Third floor staff lounge sheet floor covering			No accessible ACM
3		THIRD WEST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the washrooms throughout the wing contain an asbestos foil-faced heat shield, management of this material is recommended.
3		THIRD WEST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" It green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
3		THIRD EAST	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the washrooms throughout the wing contain an asbestos foil-faced heat shield, management of this material is recommended.
3		THIRD EAST	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" It green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
3		THIRD SOUTH	Sample Rep.	B51-ASB51	18/2/2006	Chrysotile	60%	Heat Shield Material	Bersch	Good	3	22-Incandescent light fixture heat shield material	Low	Manage	The majority of the washrooms throughout the wing contain an asbestos foil-faced heat shield, management of this material is recommended.

YORKTON UNION HOSPITAL			BERSCH & ASSOCIATES LTD.												
			Sample Data												
Room				Sample	Date	Asbestos	% of	Tradename	Sample			Description of	Potential for	Recommended	
Floor	Number	Use	Locations	ID	DD/MM/YY	Type	Asbestos	ACM Product	Auditor	Condition	Priority	Sample Location	Disturbance	Action	Comments
3		THIRD SOUTH	Sample Rep.	B51-ASB55	18/2/2006	Chrysotile	1-5%	Vinyl Asbestos Tile	Bersch	Good	3	017-9" X 9" lt green/white streak floor tile	Low	Manage	The patient rooms and corridors contain ACM floor tile refer to the door jam labels.
P	401	PENTHOUSE	Sample	B51-ASB1	18/2/2006	Chrysotile	70%	Pipeline Fitting Compound	Bersch	Moderate	2	401-Small pipeline fitting on the unit heat pipeline adjacent the rooftop doorway	Low/Mod	Encapsulate	Visible pipeline fittings present. Encapsulate 2 fittings at the unit heater adjacent the rooftop access door.
P	401	PENTHOUSE	Sample	B51-ASB2	18/2/2006	Chrysotile	30%	Woven pipeline insulation	Bersch	Good	3	401-Woven wrapping on the chiller pipeline in the southwest corner adj. the chiller	Low	Manage	
P	401	PENTHOUSE	Sample	B51-ASB3	18/2/2006	Chrysotile	60%	Pipeline Fitting Compound	Bersch	Poor/Mod	1	401-Pipelng fitting above the chilled water pump in the southwest corner adj. the chiller	Low/Mod	Remove	Visible pipeline fittings present. Remove 1 medium valve assembly leading to the chiller in the southwest corner. Remove 2 fittings on the north side of the General Supply Fan Unit on the mezzanine level. Hepa vacuum the northwest corner where debris is present on the floor.
P	401	PENTHOUSE	Sample	B51-ASB4	18/2/2006		none	Pipeline Fitting Compound	Bersch			401-Condensate pipeline fitting at the floor level to the north of the chilled water pump in the southwest corner			
P	401	PENTHOUSE	Sample	B51-ASB5	18/2/2006		none	Pipeline Fitting Compound	Bersch			401-Medium pipeline fitting adj. the access doors in the mezz. floor to the west of the stairwell			
P	401	PENTHOUSE	Sample	B51-ASB6	18/2/2006	Chrysotile	60%	Mechanical Insulation	Bersch	Poor/Mod	1	401-Supply air unit ductwork parging/insulation at the access door on the unit below the doors in the mezz. Floor	Moderate	Repair	The mud compound beneath the canvass on the fan unit contains asbestos. At minimum repair the air handling duct work insulation around the filter bank access door and the corner adjacent the door. The owner may consider removing the insulation on the side of the unit below the mezzanine. The potential for disturbance is moderate.
P	401	PENTHOUSE	Sample	B51-ASB7	18/2/2006		none	Pipeline Fitting Compound	Bersch			401-Chilled water supply pipeline fitting on the mezz. on the side of the air handling unit above the access doors in the mezz. floor			